

Throttle Return Bands – Instructions

Use 3 bands for most OS-style and similar 1/8 nitro engines.

Installation

Loop each band around the high-speed needle and below the fuel inlet nipple and around the carb slide ball end.

With the vehicle **powered off**, open the throttle fully and release it. The carb slide must quickly return to idle every time.

If return is weak or inconsistent, add another band until return is positive.

Safety

Check the bands regularly for wear or damage and replace as needed. These bands help reduce the risk of a dangerous runaway vehicle, but only when use correctly and in proper condition.